



Pos.	X	Y
1.1	20	27.23

Bohrungstabelle

Anzeigen: Koordinatenliste

Pos.	X	Y	Ø	Beschreibung	Norm
1.1	20	27.23	Ø11	Durchgangsloch	DIN EN 20273

Spalten Bohrungstabelle

1	2	Spalte	Überschrift	Breite	Formel/Format	3	4	5	6	7
<input type="checkbox"/>		ParentOrigin	Ursprung	25.00				.0	0	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>		Label	Pos.	20.00	=<Origin><IF(OR(ISBLANK(Origin),			A		<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>		X	X	20.00				<>	2	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>		Y	Y	20.00				<>	2	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>		PolarRadius	r	20.00				<>	2	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>		PolarAngle	{\fSymbol b0 i0 c2	20.00				<>	0	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>		Diameter	%%c	25.00				<>	2	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>		Description	Beschreibung	50.00				A		<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>		Standard	Norm	70.00				A		<input checked="" type="checkbox"/>
<input type="checkbox"/>		Origin	Ursprung	20.00	1			.0	0	<input checked="" type="checkbox"/>
<input type="checkbox"/>		Item	Pos.	10.00				.0	0	<input checked="" type="checkbox"/>

Spalten formatieren

(1) Sichtbar in Bohrungstabelle Kartesisch Polar

(2) Sperrungsbearbeitung Ja/Nein

(3) Überschriftausrichtung

(4) Datenausrichtung

(5) Datentyp

(6) Genauigkeit

Breite

(7) Zeilenumbruch Ja/Nein

OK Abbrechen Anwenden Hilfe

