

```

Flaecheninhalt.txt
Dim markId8 As Session.UndoMarkId
markId8 = theSession.SetUndoMark(Session.MarkVisibility.Visible, "Start")

Dim measureFaceBuilder1 As MeasureFaceBuilder
measureFaceBuilder1 =
workPart.MeasureManager.CreateMeasureFaceBuilder(nullNXObject)

measureFaceBuilder1.Infowindow = True

theSession.SetUndoMarkName(markId8, "Measure Faces Dialogfenster")

Dim added3 As Boolean
added3 = measureFaceBuilder1.FaceObjects.Add(face1)

Dim unit2 As Unit =
CType(workPart.UnitCollection.FindObject("SquareMilliMeter"), Unit)

Dim objects2(0) As IParameterizedSurface
objects2(0) = face1
Dim measureFaces1 As MeasureFaces
measureFaces1 = workPart.MeasureManager.NewFaceProperties(unit2, unit1, 0.99,
objects2)

measureFaces1.Information()
MsgBox(measureFaces1.Information())

measureFaces1.Dispose()
Dim markId9 As Session.UndoMarkId
markId9 = theSession.SetUndoMark(Session.MarkVisibility.Invisible, "Measure
Faces")

measureFaceBuilder1.FaceObjects.Clear()

theSession.DeleteUndoMark(markId9, Nothing)

theSession.SetUndoMarkName(markId8, "Measure Faces")

measureFaceBuilder1.Destroy()

```