

W2_SWB_2	1131	Change-over contact (2-path), momentary contact on actuation and release (right and left)	Change-over contact, momentary contact make, right and left	Change-over contact	Change-over contact, 3 connection points	IEC_symbol	Allpolig
W2_SWB_2	1131	Change-over contact (2-path), momentary contact on actuation and release (right and left)	Change-over contact, momentary contact make, right and left	Change-over contact	Change-over contact, 3 connection points	IEC_single_symbol	Einpilig
T2	3051	Single-phase transformer (placeholder)	Transformer, 4 connection points	Transformer	Transformer, 4 connection points	IEC_single_symbol	Einpilig
T3	3053	Three-phase transformer, star connection (placeholder)	Transformer, 6 connection points	Transformer	Transformer, 6 connection points	IEC_single_symbol	Einpilig
XBDO	3211	Female pin without cross-reference (placeholder)	Others, variable	Other	Others, variable	IEC_single_symbol	Einpilig
XSDO	3212	Pin without cross-reference (placeholder)	Others, variable	Other	Others, variable	IEC_single_symbol	Einpilig
XBDU	3213	Female pin without cross-reference (placeholder)	Others, variable	Other	Others, variable	IEC_single_symbol	Einpilig
XSDU	3214	Pin without cross-reference (placeholder)	Others, variable	Other	Others, variable	IEC_single_symbol	Einpilig
X4	3262	Terminal with 4 connection points (placeholder)	Others, variable	Other	Others, variable	IEC_single_symbol	Einpilig
M31_1	3559	Three-phase asynchronous motor	Motor without PE, variable	Motor	Motor, variable	IEC_symbol	Allpolig
M31_1	3559	Three-phase asynchronous motor (placeholder)	Motor without PE, variable	Motor	Motor, variable	IEC_single_symbol	Einpilig
Dummy	4000	(Placeholder)	Others, variable	Other	Others, variable	IEC_symbol	Allpolig