

Stückliste Eigenschaften für METSO_ISO_2D auf der... ? X

Revision: ISO 7573 - 1983 Stückliste Eigenschaften für METSO_ISO_2

<Variablen> = Quant

1	2	Spalte	Überschrift	Breite	Formel für Spalten	3	4	5	6	7	Σ	▲
<input checked="" type="checkbox"/>		NOTE	Item no/Doc no	36.00				A				<input type="checkbox"/>
<input checked="" type="checkbox"/>		ITEM	Pos no	10.00				.0	0	1		<input type="checkbox"/>
<input checked="" type="checkbox"/>		QTY	Quant	10.00				.0	0	1		<input type="checkbox"/>
<input checked="" type="checkbox"/>		DESCR	Description	29.00				A				<input type="checkbox"/>
<input checked="" type="checkbox"/>		STANDARD	Designation	34.00				A				<input type="checkbox"/>
<input checked="" type="checkbox"/>		DIM	Dimension	17.00				A				<input type="checkbox"/>
<input checked="" type="checkbox"/>		MATERIAL	Material	14.00				A				<input type="checkbox"/>
<input checked="" type="checkbox"/>		MASS	Weight	16.00				A				<input type="checkbox"/>
<input checked="" type="checkbox"/>		USER1	Description (Swe)	29.00				A				<input type="checkbox"/>
<input checked="" type="checkbox"/>		USER2	Designation (Swe)	34.00				A				<input type="checkbox"/>
<input checked="" type="checkbox"/>		USER3	Description (Fin)	29.00				A				<input type="checkbox"/>
<input checked="" type="checkbox"/>		USER4	Designation (Fin)	34.00				A				<input type="checkbox"/>

Spalten formatieren

(1) Sichtbar in Stückliste Ja/Nein

(2) Bearbeitung sperren Ja/Nein

(3) Überschriftausrichtung

(4) Datenausrichtung

(5) Datentyp **Numerisch**

(6) Genauigkeit

(7) Führende Breite

Vorgabe OK Abbrechen Anwenden Hilfe >>