




```
Dim swApp As SldWorks.Application
Dim Part As SldWorks.PartDoc

Set swApp = GetObject(, "SldWorks.Application")
Set Part = swApp.ActiveDoc

If Not Part Is Nothing Then
    InfoCount = Part.GetCustomInfoCount2("") ' wieviele Benutzerdef. Eigenschaften im akt. Teil?
    InfoNames = Part.GetCustomInfoNames2("") ' Alle Namen der Benutzerdef. Eigenschaften in ein Variant einlesen

    For D = 0 To InfoCount - 1 ' Schleife durch alle Benutzerdef. Eigenschaften
        If Not Left(InfoNames(D), 3) = "WEB" And Not Left(InfoNames(D), 3) = "VDO" Then
           RetVal = Part.DeleteCustomInfo2("", InfoNames(D)) ' Löschen aller Eigenschaften
        End If
    Next D
End If
```