

Modellparameter					
d0	mm	10 mm	10,000000	●	10,000000
d1	grad	0,0 grad	0,000000	●	0,000000
AnzahlderAnordnung	oE	Formel	1,000000	●	1,000000
d4	mm	10 mm	10,000000	●	10,000000
Benutzerparameter					
Durchmesser	mm	50 mm	50,000000	●	50,000000
Formel	oE	floor((Grenzwert / Durchmesser) + 1 oE)	1,000000	●	1,000000
Grenzwert	mm	1 mm	1,000000	●	1,000000

d0	mm	10 mm	10,000000	●	10,000000
d1	grad	0,0 grad	0,000000	●	0,000000
AnzahlderAnordnung	oE	Formel	2,000000	●	2,000000
d4	mm	10 mm	10,000000	●	10,000000
Benutzerparameter					
Durchmesser	mm	50 mm	50,000000	●	50,000000
Formel	oE	floor((Grenzwert / Durchmesser) + 1 oE)	2,000000	●	2,000000
Grenzwert	mm	51 mm	51,000000	●	51,000000