

	1		
	Passmaß	Abmaß	
	30 H7	+0,021 0,000	
	50	0,025 0,000	
	<div>Anfügepunkt eingeben:</div> <div><div>-0,010</div><div>-0,029</div></div>		D